

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/14/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 12/10/2012 – 0700, 12/22/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston
8. Activity Log			
Time	Major Events		
0800	<ul style="list-style-type: none"> Attended the internal C&G meeting 		
0900	<ul style="list-style-type: none"> Arrived at C0.4 Boat launch. MP4.5 no sheen observed. MP5.60 LDB ice observed forming. MP5.60 LDB observed sheen and tar globs. MP5.63 LDB ice observed forming. MP5.63 LDB below the railroad trestles observed sheen and tar globs. MP5.75 LDB observed sheen and tar globs. Ceresco Dam impoundment observed a bathymetry team. MP5.63 – MP5.75 RDB observed ice. MP12.5 observed an RI crew. MP15.25 South Mill Pond sheen and tar globs observed within the ice. Observed CSC sampling at the C3.2 Pole Barn. Observed core logging and sampling at the C3.2 Pole Barn. MP21.5 Sediment trap observed a bathymetry team. Morrow Lake Delta observed CSD sampling. Morrow Lake Delta observed one of three bathymetry teams. Morrow Lake Delta observed the second of three bathymetry teams. Morrow Lake Delta observed the third of three bathymetry teams. Morrow Lake south cove observed sheen and tar globs. Morrow Lake north cove observed ice forming. MP36.5 RDB no sheen observed. 		
1600	Returned to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			